

Title

# Dongle migration from CodeMeter

Description

You can migrate your dongle by the following steps.

## Topics

Preparation.....	2
Check a firmware version .....	3
Firmware update .....	5
Migrate your dongle .....	10


## Preparation

1. Connect your CodeMeter dongle to USB port of your host PC.
2. Startup dSPACE Installation Manager from start menu.  
(Start menu -> dSPACE Installation Manager -> dSPACE Installation Manager)

## Check a firmware version


Check if your dongle is required a Firmware Update.

1. Open "License" tab at the top of the screen.
2. Open "License Administration" tab.
3. Select "Dongle Migration"
4. Click "Next" button.




Then the dongle information will be displayed.

\*If dongle information does not appear, click "Rescan" button.



5. Check the status displayed in the "Firmware Update" column.




The next step depends on the status of your dongle.

Select the following link according to the displayed status.


Status	Link	Remarks
Required	<a href="#">Firmware update</a>	Require updating your dongle firmware.
not required	<a href="#">Migrate your dongle</a>	Firmware update is not required.

## Firmware update


1. Check the checkbox on "Migrate" column.
2. Click "Update Firmware" button.



3. Click "Yes" button in the "Update firmware" dialog.




- Click "OK" button in the "Press Rescan Button when finished" dialog.




CodeMeter Control Center will be started up.

- Click "Update Firmware of selected CmDongle" button.




6. Click "OK" button in the "CodeMeter" dialog.




7. Wait till the firmware update is done.

\*Do not remove your dongle during this updating.




The following dialog will be displayed when the firmware update is done.

8. Click "OK" button.




Update your dongle time information.

9. Open "Process" menu.
10. Select "Update Time Certificates".




11. Wait till the update is done.




The update is done when the following dialog is displayed.

12. Click "Yes" button,






13. Close CodeMeter Control Center
14. Click "Rescan" button and update information with dSPACE Installation Manager.




Firmware update is completed when the status changes to "not required"  
Then, go on the next page and migrate your dongle.

## Migrate your dongle

1. Select Migrate from old CmDongle, check the check box on "Migrate" column.
2. Click "Finish" button.



3. Click "Yes" button on the "Migrate CmDongle?" dialog.



The migration procedures will be completed when you see the message "Migration Completed"

